



Above--Runout tests confirmed the part inboard shaft was bent. Yardworkers in foreground discuss its removal.



Left--Yardworker grinds clean a channel adjacent to the wooden flight deck.