





Gunnery

Gurmery Department is composed of many divisions including the Deck Divisions and Marine Detachment. Gurmery Dept. is responsible for all types of weapons used on beard ship, and in aircraft, as well as being responsible for all boats, lines and tackle used in and about the ship.

The Deck Divisions are numbered one through four. Their chief responsibility is taking care of the quarterieck area, manning refueling stations, handling mooring lines, and maintaining the boat booms and accommodation ladders. They also maintain and run liberty boats while in port and provide ym cryss and beliamse.

In the Ordinace Group is Fifth Division which cares for and maintains the seven 57/36 caliber batteries and their associated magazines and space. Fox Division is in charge of fire control. This entails proper coeration, maintenance and recair of

the ship's fire control and gun laying equipment. Ourser's Bates and Aviation Ordaneceme make up the two main sections of Division. The Ourser's proper stonage and accounting for all ordanece corries on lower with the exception of Special Memorania to lower that the exception of Special Memorania to the Aviation Orlaneceme have the glo of operating and maintaining all home and assumition to Aviation of the Control of the Control of Special Memorania of the Control o

EOD (Explosive Ordnance Disposal) is also a part of G Division. They check any ordnance which has been bumped or jarred during handling and also do

the ship's diving.
W Division is responsible for nuclear weapons on board.

The Marine Detachment provides an internal and external security guard and orderlies.